

TACHO-UNIVERSAL

## TACHO UNIVERSAL

Dear Sirs,

Thank you for your interest in our product.

The Tacho-Universal is the most complete available programming device for digital speedometers. The system is a high-quality tool, which offers a maximum of flexibility and working comfort despite simple operation.

Outstanding characteristics of the system are:

- The current odometer reading is decoded and indicated.
- Intuitive operability by clear menu guidance.
- Light display.
- Menu guidance in different languages (D, E ,F ,I ,ESP ,POL, ....)
- All data can be edited, stored and loaded.
- The stored data can be transferred to a PC for archiving.
- Defective speedometers can be comfortably repaired.
- You can download developed software directly through our internet server.
- New types and marks can be de-energized within seconds by telephone.
- The annoying post office dispatch of the equipment is void.

With purchase a briefing and a constant telephone support are natural for questions and problems by us.

These versions you can supplement at will with other models.

Contained in each case are the TACHO UNIVERSAL, all necessary plugs, cable, guidance's (detailed CD with guidance for all models), special tools, etc... Further we stand for our customers always for questions for order, both by E-Mail and by telephone.

If you should wish an individual software package, communicate to us please, which models you need and we create you an offer.

I hope, this offer is interesting to you. For further questions please contact us.

Yours sincerely,

The TACHO-UNIVERSAL: Each package contains the Tacho-Universal all necessary plugs, cables, guidance (cd with manuals for all models)



References to the Tacho Universal:

**Diagnosis-plug:** programming is made in few seconds by the Diagnosis-Plug interface of the vehicle.

**Cluster-plug:** the removed cluster is connected and programmed with the Tacho-Universal

**Directly:** the Cluster must be removed and opened for programming. Partly soldering work is necessary.

Programming techniques:

diagnosis-plug:	programming without removing the cluster
cluster-plug:	programming without opening the cluster
eeprom:	programming the eeprom by clip
soldering contacts:	programming by soldering contacts on the circuit board
processor:	processor direct programming

TACHO-UNIVERSAL

[www.autocardiag.com](http://www.autocardiag.com)

TACHO-UNIVERSAL

Manufacturer	Model	Version	Method	V1	V2
Alfa Romeo	145	old	Processor		
		new	Processor		
	146	old	Processor		
		new	Processor		
	147		Eeprom		
	156	before 2002	Cluster-Plug		
		since 2002	Cluster-Plug		
	166		Processor		
		Model 2002	Eeprom		
Spider		Processor			
GTV		Processor			

Manufacturer	Model	Version	Method	V1	V2		
Audi	A2	VDO	Eeprom				
		VDO	Cluster-Plug				
		VDO	Diagnosis-Plug				
		VDO Model 2002	Eeprom				
	A3/S3	VDO Model 2002	VDO	Eeprom			
			VDO	Diagnosis-Plug			
		UKNSI	UKNSI	Eeprom			
			VDO since 2000	Eeprom			
		VDO ab2000	VDO ab2000	Cluster-Plug			
			VDO since 2000	Diagnosis-Plug			
		Jaeger before 6/2001	Jaeger before 6/2001	Cluster-Plug			
			Jaeger before 6/2001	Cluster-Plug			
		Jaeger since 7/2001	Jaeger since 7/2001	Cluster-Plug			
			Jaeger	Diagnosis-Plug			
		VDO Model 2002	VDO Model 2002	Eeprom			
			VDO Model 2002	Diagnosis-Plug			
		A4/S4	VDO old	VDO old	direkt		
				VDO old	Diagnosis-Plug		
			VDO old MFA	VDO old MFA	Eeprom		
				VDO old MFA Version 1	Diagnosis-Plug		
			VDO old MFA Version 2	VDO old MFA Version 2	Diagnosis-Plug		
				VDO new	Eeprom		
			VDO new	VDO new	Diagnosis-Plug		
				UKNSI old	Eeprom		
	UKNSI new		UKNSI new	Eeprom			
			UKNSI 2 Eeproms	Eeprom			
	VDO since 2000		VDO since 2000	Eeprom			
			VDO since 2000	Cluster-Plug			
	VDO since 2000		VDO since 2000	Diagnosis-Plug			
			Jaeger	Cluster-Plug			
	Jaeger before 6/2001		Jaeger before 6/2001	Cluster-Plug			
			Jaeger	Diagnosis-Plug			
	Bosch 2001	Bosch 2001	Eeprom				
		Bosch 2001	Diagnosis-Plug				

TACHO-UNIVERSAL

	Bosch 2002	Eeprom		
<b>A6/S6</b>	VDO old	Eeprom		
	VDO old	Diagnosis-Plug		
	VDO new	Eeprom		
	VDO new	Diagnosis-Plug		
	VDO since 2000	Eeprom		
	VDO since 2000	Cluster-Plug		
	VDO since 2000	Diagnosis-Plug		
	Jaeger before 6/2001	Cluster-Plug		
	Jaeger before 6/2001	Cluster-Plug		
	Jaeger since 7/2001	Cluster-Plug		
	Jaeger	Diagnosis-Plug		
	VDO Model 2002	Eeprom		
	VDO Model 2002	Diagnosis-Plug		
<b>A8/S8</b>	VDO Version 1	Eeprom		
	VDO Version 1	Diagnosis-Plug		
	VDO Version 2	Eeprom		
	VDO Version 2	Diagnosis-Plug		
	VDO since 1999 Version 1	Eeprom		
	VDO since 1999 Version 2	Eeprom		
<b>TT</b>	Jaeger	Diagnosis-Plug		
	Jaeger since 2000	Cluster-Plug		
	Jaeger before 6/2001	Cluster-Plug		
	Jaeger since 7/2001	Cluster-Plug		
	Jaeger since 2000	Diagnosis-Plug		
<b>Service-Display</b>	all models	Diagnosis-Plug		
<b>TV-Unlocking</b>		Manual		

<b>BMW</b>	<b>3er E36</b>	before SW 23	Diagnosis-Plug		
		SW 24	Cluster-Plug		
	<b>3er E36 Compact</b>	SW 20	Cluster-Plug		
		SW 6+7	Cluster-Plug		
		SW 9+10	Eeprom		
		SW 9+10	Cluster-Plug		
	<b>3er E46</b>	before SW 16	Eeprom		
		before SW 16	Diagnosis-Plug		
		Service-Display	Eeprom		
		since SW 17 without eeprom replacing	Soldering contacts		
	<b>5er E34</b>	Codeplug brown	Eeprom		
		Codeplug blue	Eeprom		
		Codeplug green	Eeprom		
	<b>5er E39</b>	low	Eeprom		
		low	Diagnosis-Plug		
low SW 15		Diagnosis-Plug			

TACHO-UNIVERSAL

	low SW 16	Diagnosis-Plug		
	low since SW 17 without eeprom replacing	Soldering contacts		
	high + IKE	Eeprom		
	high + IKE	Diagnosis-Plug		
	high - IKE	Cluster-Plug		
	high - IKE SW 13	Soldering contacts		
	high - IKE since SW 14 without eeprom replacing	Soldering contacts		
<b>7er E32</b>	Codeplug brown	Eeprom		
	Codeplug blue	Eeprom		
	Codeplug green	Eeprom		
<b>7er E38</b>	low	Eeprom		
	low	Diagnosis-Plug		
	low SW 15	Diagnosis-Plug		
	low SW 16	Diagnosis-Plug		
	low since SW 17 without eeprom replacing	Soldering contacts		
	high + IKE	Eeprom		
	high + IKE	Diagnosis-Plug		
	high - IKE	Cluster-Plug		
	high - IKE SW 13	Soldering contacts		
	high - IKE since SW 14 without eeprom replacing	Soldering contacts		
<b>8er E31</b>		Eeprom		
		Diagnosis-Plug		
<b>Z3</b>	SW 20	Cluster-Plug		
	SW 6+7	Cluster-Plug		
	SW 9+10	Eeprom		
	SW 9+10	Cluster-Plug		
<b>X3</b>		Eeprom		
<b>X5</b>	high - IKE SW 13	Soldering contacts		
	high - IKE since SW 14 without eeprom replacing	Soldering contacts		
<b>Z8</b>		Eeprom		
<b>TV-Unlocking</b>	MK I + MK II (before 1999)	Manual		
	MK III (since 2000)	Diagnosis-Plug		
<b>F650 GS</b>		Eeprom		
<b>C1</b>		Eeprom		

<b>Citroen</b>	<b>Xsara</b>		Eeprom		
	<b>Xsantia</b>		Eeprom		
	<b>Berlingo</b>	2003 cluster + BSI	Eeprom		
	<b>C3</b>		Eeprom		
	<b>C5</b>	Model 2001 BSI	Soldering contacts		
	<b>C5</b>	Model 2002 cluster + BSI	Soldering contacts		
	<b>C5</b>	BSI Valeo	Eeprom		

## TACHO-UNIVERSAL

<b>C8</b>	3 modules	Eeprom + Soldering contacts		
<b>Dispatch</b>		Processor		
<b>Evasion</b>		Processor		
<b>Jumper</b>		Eeprom		
<b>Jumpy</b>	V1	Processor		
	V2	Processor		
<b>Picasso</b>	2004 cluster + BSI	Eeprom		
<b>Saxo</b>		Cluster-Plug		
<b>Synergie</b>		Processor		

<b>Cagiva</b>	<b>Raptor</b>		Eeprom	
---------------	---------------	--	--------	--

<b>Chrysler</b>	<b>Cherokee</b>		Eeprom	
		Model 2002	Soldering contacts	
		Model 2003	Soldering contacts	
	<b>Crossfire</b>		Diagnosis-Plug	
	<b>Grand Cherokee</b>	before 3/1999	Diagnosis-Plug	
		4/1999 - 2002	Cluster-Plug	
		since 2002 (912)	Soldering contacts	
	<b>Neon</b>		Soldering contacts	
	<b>PT Cruiser</b>		Processor	
		Model 2002 (912)	Soldering contacts	
	<b>Stratus</b>	before 1999	Diagnosis-Plug	
		since 1999	Diagnosis-Plug	
	<b>Wrangler</b>		Eeprom	
	<b>Voyager</b>	before 1999	Diagnosis-Plug	
		since 1999	Diagnosis-Plug	
	Model 2002 (912)	Soldering contacts		
<b>SRI-Speicher</b>	all models	Diagnosis-Plug		

<b>Daihatsu</b>	<b>YRV</b>		Eeprom	
	<b>Terios</b>		Eeprom	

<b>Ferrari</b>	<b>360 Modena</b>		Eeprom	
	<b>550 Maranello</b>		Eeprom	

<b>Fiat</b>	<b>Brava</b>	ST	Processor	
		Custom	Processor	
		908 Version 1	Processor	
		908 Version 2	Processor	
		UKNSI	Eeprom	
	<b>Bravo</b>	ST	Processor	
		Custom	Processor	
		908 Version 1	Processor	
		908 Version 2	Processor	
		UKNSI	Eeprom	
	<b>Doblo</b>	Version 1	Processor	
		Version 2	Processor	
		NEC	Eeprom	

TACHO-UNIVERSAL

	2004	Eeprom		
Ducato	Nec 2002	Eeprom		
Marea	MM3S	Processor		
	C(QAF/OPT)	Processor		
	P(68H)	Processor		
Multipla		Eeprom		
	Model 2002	Eeprom		
Palio	Version 1	Processor		
	Version 2	Processor		
Panda		Eeprom		
Punto	2000 Version 1	Soldering contacts		
	2000 Version 2	Soldering contacts		
	2000 Version 3	Soldering contacts		
	2001 Version 1	Soldering contacts		
	2001 Version 2	Soldering contacts		
	2001 Version 3	Soldering contacts		
	2002 Nec	Eeprom		
	2003 Nec	Eeprom		
	CAN	Cluster-Plug		
Scudo	Version 1	Processor		
	Version 2	Processor		
Seicento	NEC	Processor		
Stilo	912	Soldering contacts		
Tempra	Tempra	Eeprom		
	Borg	Eeprom		
	Veglia	Eeprom		
Tipo	Borg	Eeprom		
	Veglia	Eeprom		
Ulysse		Processor		
	2004 - 3 modules	Eeprom/Soldering contacts		

Ford	Cougar		Processor		
	Connect		Soldering contacts		
	Escort	Version 1	Soldering contacts		
		Version 2	Soldering contacts		
	Fiesta	Version 1	Soldering contacts		
		Version 2	Soldering contacts		
		Model 2002	Eeprom		
	Focus	Version 1	Cluster-Plug		
		Version 2	Cluster-Plug		
		Model 2003	Eeprom		
	Focus RS		Soldering contacts		
	Fusion		Eeprom		
	Galaxy	before Model 2001	Diagnosis-Plug		
		since Model 2001 Version 1	Eeprom		
		since Model 2001 Version 2	Eeprom		
		since Model 2001 Version 1+2	Diagnosis-Plug		
		since Model 2002	Diagnosis-Plug		
	Maverick		Processor		



## TACHO-UNIVERSAL

Mondeo		Soldering contacts		
Puma		Soldering contacts		
Ranger		Soldering contacts		
Scorpio		Cluster-Plug		
Transit	-2003	Eeprom		
	2003	Eeprom		

<b>GMC</b>	Seville STS		Eeprom		
------------	-------------	--	--------	--	--

<b>Harley-Davidson</b>	alle	Model 2001	Eeprom		
	alle	Model 2002	Eeprom		

<b>Hyunday</b>	Santa Fe	Version 1	Eeprom		
		Version 2	Eeprom		
	Coupe		Eeprom		
	Getz		Eeprom		
	Accent		Eeprom		
	Matrix		Eeprom		
	XG 30		Eeprom		

<b>Honda</b>	Accord		Eeprom		
		705 Processor	Processor		
		2003	Soldering contacts		
	Civic		Eeprom		
	CRV		Eeprom		
	Fireblade		Eeprom		
	HRV		Eeprom		
	Jazz		Eeprom		
	Legend		Eeprom		
	Logo		Eeprom		
	Shuttle		Eeprom		
	Stream		Eeprom		
	S2000		Eeprom		
	VFR 800		Eeprom		
	VFR 1000		Eeprom		
	VT 1100		Eeprom		

<b>Isuzu</b>	Trooper		Eeprom		
	Pickup		Eeprom		

<b>Iveco</b>	Daily		Eeprom		
--------------	-------	--	--------	--	--

<b>Jaguar</b>	Daimler/XJ	11DU Version 1	Cluster-Plug		
		11DU Version 2	Cluster-Plug		
		11DU Version 3	Cluster-Plug		
	XK8	before 2000	Soldering contacts		
		since 2000	Soldering contacts		
		since 2003	Processor		
	X-Type	Version 1	Soldering contacts		
		Version 2	Soldering contacts		
	S-Type				
		Model 2003	Processor		

## TACHO-UNIVERSAL

<b>Kawasaki</b>	GPZ 600		Eeprom		
	ZX 6		Eeprom		
	ZX 6R		Eeprom		
		2003	Eeprom		
	ZX 9		Eeprom		
	ZX 9R		Eeprom		
	ZX 12R		Eeprom		

<b>Kia</b>	Carens		Eeprom		
	Carnival		Eeprom		
	Rio		Eeprom		
	Sportage		Eeprom		
	Sorento		Eeprom		

<b>Lancia</b>	Kappa		Soldering contacts		
	Lybra	Version 1	Soldering contacts		
		Version 2	Soldering contacts		
		Version 3	Soldering contacts		
	Y	Version 1	Soldering contacts		
		Version 2	Soldering contacts		
		Version 3	Soldering contacts		
		Version 4	Processor		
		Version 5 SC51 Processor	Processor		

<b>Lexus</b>	GS 300		Eeprom		
	Harrier Jeep		Eeprom		
	IS 200		Eeprom		
	LS 200		Eeprom		
	LS 300		Eeprom		
	LS 400		Eeprom		
	LX 470		Eeprom		
		Model 2002	Eeprom		
	RX 300		Eeprom		
	SC 400		Eeprom		

<b>Landrover</b>	Defender		Eeprom		
	Discovery	before 6/2001	Processor		
		since 6/2001	Processor		
	Freelander	UKNSI+C567	Eeprom		
		VDO 2002	Eeprom		
	Range Rover	Model 2002	Eeprom		
	TD 5	before 6/2001	Processor		
since 6/2001		Processor			

<b>Lincoln</b>	Towncar		Processor	Auf Anfrage	
		1995	Processor		
		before 1999	Processor		
		since 1999	Processor		

## TACHO-UNIVERSAL

<b>MAN</b>	Truck	without tachograph	Eeprom		
------------	-------	--------------------	--------	--	--

<b>Mazda</b>	121		Eeprom		
	323	Version 1	Eeprom		
		Version 2	Eeprom		
		Version 3	Eeprom		
	3		Eeprom		
	626	Version 1	Eeprom		
		Version 2	Eeprom		
		Version 3	Eeprom		
	6		Eeprom		
	Demio		Eeprom		
	E2200		Eeprom		
	MPV		Eeprom		
	MX 5		Eeprom		
	Pickup B2500		Eeprom		
	Premacy		Eeprom		
	Tribute		Processor		
Xedos 9		Eeprom			

<b>Mercedes</b>	A-Klasse	before Model 2000	Diagnosis-Plug		
		since Model 2000	Cluster-Plug		
		since Model 2000	Diagnosis-Plug		
	C-Klasse (W202)	VDO – 9/1995	Eeprom		
		VDO -9/1995	Cluster-Plug		
		MotoMeter – 9/1995	Eeprom		
		MotoMeter – 9/1995	Cluster-Plug		
		9/1995 -4/1998 Version 1	Eeprom		
		9/1995 -4/1998 Version 2	Eeprom		
		9/1995 -4/1998 Version 1+2	Diagnosis-Plug		
		since 4/1998	Eeprom		
		since 4/1998	Diagnosis-Plug		
		C-Klasse (W203)	Cluster	Eeprom	
	Cluster		Cluster-Plug		
	Ignition lock Version 1		Processor		
	Ignition lock Version2		Processor		
	Ignition lock since 5/2001		Processor		
	Flash cluster		Cluster-Plug		
	CL (W140)	before 6/1996	Eeprom		
		before 6/1996	Cluster-Plug		
		6/1996 –4/1998 Version 1	Eeprom		
		6/1996 –4/1998 Version 2	Eeprom		

TACHO-UNIVERSAL

	6/1996 –4/1998 Version 1+2	Diagnosis-Plug		
	since 4/1998	Eeprom		
	since 4/1998	Diagnosis-Plug		
<b>CL (W215)</b>	before 2000	Eeprom		
	before 5/2001	Eeprom		
	Ignition lock since 5/2001 Version 1	Processor		
	Ignition lock since 5/2001 Version 2	Processor		
	Ignition lock Model 2002	Processor		
	Service-Display	Eeprom		
<b>CLK</b>	before 4/1998 Version 1	Eeprom		
	before 4/1998 Version 2	Eeprom		
	before 4/1998 Version 1+2	Diagnosis-Plug		
	4/1998 –7/1999	Eeprom		
	4/1998 –7/1999	Diagnosis-Plug		
	since 7/1999	Eeprom		
	since 7/1999	Diagnosis-Plug		
<b>E-Klasse</b>	before 4/1998 Version 1	Eeprom		
	before 4/1998 Version 2	Eeprom		
	before 4/1998 Version 1+2	Diagnosis-Plug		
	4/1998 –7/1999	Eeprom		
	4/1998 –7/1999	Diagnosis-Plug		
	since 7/1999	Eeprom		
	since 7/1999	Diagnosis-Plug		
	W211	Cluster-Plug		
<b>G-Klasse</b>		Eeprom		
		Diagnosis-Plug		
<b>M-Klasse</b>		Eeprom		
		Diagnosis-Plug		
<b>S-Klasse (W140)</b>	before 6/1996	Eeprom		
	before 6/1996	Cluster-Plug		
	6/1996 –4/1998 Version 1	Eeprom		
	6/1996 –4/1998 Version 2	Eeprom		
	6/1996 –4/1998 Version 1+2	Diagnosis-Plug		
	since 4/1998	Eeprom		
	since 4/1998	Diagnosis-Plug		
<b>S-Klasse (W220)</b>	before 2000	Eeprom		
	before 5/2001	Eeprom		
	Ignition lock since 5/2001 Version 1	Processor		
	Ignition lock since 5/2001 Version 2	Processor		
	Ignition lock Model 2002	Processor		

TACHO-UNIVERSAL

	Service-Display	Eeprom		
<b>SL (R129)</b>	before 6/1996	Eeprom		
	before 6/1996	Cluster-Plug		
	6/1996 –4/1998 Version 1	Eeprom		
	6/1996 –4/1998 Version 2	Eeprom		
	6/1996 –4/1998 Version 1+2	Diagnosis-Plug		
	since 4/1998	Eeprom		
	since 4/1998	Diagnosis-Plug		
<b>SL (R230)</b>	cluster	Eeprom		
	Ignition lock	Processor		
	Ignition lock Model 2002	Processor		
<b>SLK</b>	before 4/1998 Version 1	Eeprom		
	before 4/1998 Version 2	Eeprom		
	before 4/1998 Version 1+2	Diagnosis-Plug		
	since 4/1998	Eeprom		
	since 4/1998	Diagnosis-Plug		
<b>Sprinter</b>	VDO before 1999 Version 1	Eeprom		
	VDO before 1999 Version 2	Eeprom		
	VDO before 1999 Version 1+2	Cluster-Plug		
<b>Working hours</b>	VDO before 1999	Eeprom		
	VDO since 2000	Eeprom		
	Kienzle before 1999	Eeprom		
		Diagnosis-Plug		
	Kienzle since 2000	Eeprom		
	Magneti Marelli Version 1	Processor		
	Magneti Marelli Version 2	Processor		
	Magneti Marelli	Diagnosis-Plug		
<b>Vito</b>	VDO before 1999 Version 1	Eeprom Version 1		
	VDO before 1999 Version 2	Eeprom Version 2		
	VDO before 1999 Version 1+2	Cluster-Plug		
<b>Betriebsstunden</b>	VDO before 1999	Eeprom		
	VDO since 2000	Eeprom		
	Magneti Marelli Version 1	Processor		
	Magneti Marelli Version 2	Processor		
	Magneti Marelli	Diagnosis-Plug		
	2004 cluster + Ignition lock	Eeprom + Soldering contacts		
<b>Service-Display</b>	all models before 4/1998	Diagnosis-Plug		
	all models since 4/1998	Diagnosis-Plug		

## TACHO-UNIVERSAL

<b>Mitsubishi</b>	<b>Spacegear</b>		Eeprom		
		Yazaki	Eeprom		
	<b>Spacewagon</b>		Eeprom		
	<b>Spacestar</b>		Eeprom		
	<b>Spacerunner</b>		Eeprom		
	<b>Charisma</b>		Eeprom		
	<b>Colt</b>		Eeprom		
	<b>Lancer</b>		Eeprom		
	<b>Outlander</b>		Eeprom		
	<b>Pajero</b>	Version 1	Eeprom		
		Version 2	Eeprom		
	<b>Pinin</b>		Eeprom		
	<b>Shogun</b>	Version 1	Eeprom		
	Version 2	Eeprom			

<b>Nissan</b>	<b>Almera</b>	before Model 1999	Eeprom		
		Model 2000 Version 1	Eeprom		
		Model 2000 Version 2	Eeprom		
		Model 2001	Eeprom		
	<b>Cabstar</b>		Soldering contacts		
	<b>Infinity</b>		Eeprom		
	<b>Maxima</b>	before Model 1999	Eeprom		
		since Model 2000	Eeprom		
	<b>Micra</b>	before 2002	Eeprom		
		since 2003	Eeprom		
	<b>Primera</b>	before Model 1999	Eeprom		
		Model 1999	Eeprom		
		Model 2000	Eeprom		
		Model 2001	Eeprom		
	<b>Patrol</b>		Eeprom		
	<b>Pickup</b>		Eeprom		
		Model 2002	Eeprom		
		Model 2003	Eeprom		
	<b>Nawaro</b>		Eeprom		
	<b>Pathfinder</b>	before Model 2000	Eeprom		
		since Model 2000	Eeprom		
	<b>Skyline</b>		Eeprom		
	<b>Xtrail</b>		Eeprom		
	<b>Terrano</b>		Eeprom		
		Model 2002	Eeprom		
	<b>350 ZX</b>		Eeprom		

<b>Opel</b>	<b>Astra</b>	VDO	Eeprom		
		VDO	Diagnosis-Plug		
		VDO Model 2002	Diagnosis-Plug		
		TRW	Eeprom		
		Model 2004	Eeprom		
	<b>Corsa</b>		Diagnosis-Plug		

## TACHO-UNIVERSAL

<b>Combo</b>		Diagnosis-Plug		
<b>Frontera</b>	VDO	Eeprom		
	VDO	Diagnosis-Plug		
	TRW	Eeprom		
	Delco	Eeprom		
<b>Vectra</b>	VDO before 3/1999	Eeprom		
	VDO before 3/1999	Diagnosis-Plug		
	VDO since 3/1999	Eeprom		
	VDO since 3/1999	Diagnosis-Plug		
	Model 2002	Eeprom		
<b>Meriva</b>		Diagnosis-Plug		
<b>Monterey</b>		Eeprom		
<b>Movano</b>		Eeprom		
<b>Omega</b>		Eeprom		
<b>Signum</b>		Eeprom		
<b>Vivaro</b>		Eeprom		
<b>Zafira</b>	VDO	Eeprom		
	VDO	Diagnosis-Plug		
	VDO Model 2002	Diagnosis-Plug		
	TRW	Eeprom		

Peugeot				
<b>106</b>		Cluster-Plug		
<b>206</b>	before 2001	Processor		
	before 2001	Cluster-Plug		
	Service -2001	Cluster-Plug		
	Nec 2002 cluster + BCU	Eeprom		
	Nec 2003 cluster + BCU	Eeprom		
	BCU Autodetect			
<b>306</b>	Version 1	Eeprom		
	Version 2	Eeprom		
<b>306</b>		Cluster-Plug		
<b>307</b>	V1	Soldering contacts		
	V2	Soldering contacts		
	V3	Soldering contacts		
	2003	Eeprom		
<b>406</b>	Sagem	Eeprom		
	Jaeger	Processor		
	VDO Version 1 cluster + BCU	Eeprom		
	VDO Version 2 cluster + BCU	Eeprom		
	VDO Version 3 cluster + BCU	Eeprom		
	BCU 95040	Eeprom		
<b>607</b>	Tacho + BCU	Eeprom		
		Cluster-Plug		
<b>806</b>		Processor		
		Cluster-Plug		
<b>807</b>	3 modules	Eeprom + Soldering contacts		
<b>Boxer</b>		Eeprom		

## TACHO-UNIVERSAL

<b>Expert</b>		Processor		
---------------	--	-----------	--	--

<b>Porsche</b>	<b>928</b>		Eeprom		
	<b>996</b>	before Model 2000	Eeprom		
		before Model 2000	Diagnosis-Plug		
		since Model 2000	Eeprom		
		BCU since 2000	Eeprom		
	<b>Boxster</b>	before Model 2000	Eeprom		
		before Model 2000	Diagnosis-Plug		
		since Model 2000	Eeprom		
	<b>Cayenne</b>		Eeprom		
	<b>Turbo</b>		Eeprom		

<b>Renault</b>	<b>Clio</b>	Sagem before Model 1999	Eeprom		
		Sagem since Model 1999	Additional information		
		Sagem 2002 (NEC)	Eeprom		
		Jaeger	Eeprom		
		Jaeger 908	Processor		
		Jaeger 908	Cluster-Plug		
	<b>Espace</b>	since Model 2000 cluster + BCU Version 1	Processor		
		since Model 2000 cluster + BCU Version 2	Processor		
		2003 V1	Eeprom		
		2003 V2	Eeprom		
	<b>Kangoo</b>		Eeprom		
		908	Processor		
		908	Cluster-Plug		
		since Model 2003	Eeprom		
	<b>Laguna</b>	Sagem	Eeprom		
	<b>Laguna 2001</b>	908	Processor		
		912	Soldering contacts		
	<b>Master</b>		Eeprom		
	<b>Megane</b>	Sagem before Model 1999 Version 1	Eeprom		
		Sagem before Model 1999 Version 2	Eeprom		
		Sagem since Model 1999	Additional information		
		Sagem 2002 (NEC)	Eeprom		
		Jaeger	Processor		
		Jaeger 908	Processor		
		Jaeger 908	Cluster-Plug		
		Visteon V1	Eeprom		
		Visteon V2	Eeprom		
		Sagem 2004	Eeprom		



TACHO-UNIVERSAL

<b>Scenic</b>	Sagem before Model 1999 Version 1	Eeprom		
	Sagem before Model 1999 Version 2	Eeprom		
	Sagem since Model 1999	Additional information		
	Sagem 2002 (NEC)	Eeprom		
	Jaeger	Processor		
	Jaeger 908	Processor		
	Jaeger 908	Cluster-Plug		
	Visteon	Eeprom		
<b>Safrane</b>	Version 1	Eeprom		
	Version 2	Eeprom		
	Version 3	Eeprom		
	Version 4	Eeprom		
<b>Twingo</b>	VDO before Model 2000	Processor		
	VDO since Model 2001	Processor		
	Borg before Model 2000	Processor		
	Borg since Model 2001	Processor		
<b>Traffic</b>		Eeprom		
<b>Vel Satis</b>		Soldering contacts		

<b>Rover</b>	25		Eeprom		
	45		Eeprom		
	75		Eeprom		
	Minicooper	Cluster + LKM	Soldering contacts		
	MGF		Eeprom		

<b>Saab</b>	93	Version 1	Eeprom		
		Version 2	Eeprom		
		Model 2003	Eeprom		
	95	Version 1	Eeprom		
		Version 2	Eeprom		

<b>Seat</b>	All models	are identically	with Volkswagen!		
	Toledo	Model 2002	Eeprom		
	Leon 2002		Eeprom		
	Ibiza	TRW 2003	Eeprom		
		Model 2002 VDO	Diagnosis-Plug		
		Model 2002 VDO	Eeprom		

<b>Skoda</b>	All models	are identically	with Volkswagen!		
--------------	------------	-----------------	------------------	--	--

<b>Smart</b>	Smart		Eeprom + Processor		
	Roadster		Eeprom + Soldering contacts		

<b>Subaru</b>	Forester		Eeprom		
		Model 2002	Eeprom		

## TACHO-UNIVERSAL

	2003	Eeprom		
Impreza	before 2002	Eeprom		
	since 2002	Eeprom		
Legacy		Eeprom		
	Model 2004	Eeprom		
Outback				
	2003	Eeprom		
	2004	2X Eeprom		

Suzuki	GSX-R 750		Eeprom		
	GSX-R1000		Eeprom		
	Bandit		Eeprom		
	Burgmann		Eeprom		
	Hayabusa		Eeprom		
	Ignis		Eeprom		
	Jimny	Maneti Marelli 908	Processor		
	Jimny	Denso	Eeprom		
	Liana		Eeprom		
	TL 1000		Eeprom		
	Vitara		Eeprom		
	XF 650		Eeprom		

Toyota	Avensis		Eeprom		
		2003	Eeprom		
	Picnic		Eeprom		
	Camry		Eeprom		
	Celica		Eeprom		
	Hiace		Eeprom		
	HJ100		Eeprom		
	RAV 4		Eeprom		
	Yaris		Eeprom		
		Model 2003	Eeprom		
	Corolla		Eeprom		
		Model 2002	Eeprom		
	Corolla Verso		Eeprom		
	Landcruiser	Version 1	Eeprom		
		Version 2	Eeprom		
		Model 2001	Eeprom		
		Model 2002	Eeprom		
	Previa		Eeprom		
	Prius		Eeprom		
Prado		Eeprom			
MR 2		Eeprom			

Volvo	V40/S40		Eeprom		
	S60	912 80 Pin	Processor		
		912 112 Pin	Processor		
	V70/S70	Before Model 1999	Eeprom		
		since Model 1999 (908)	Processor		
		since Model 2001 (912) 80	Processor		

## TACHO-UNIVERSAL

	Pin			
	since Model 2001 (912) 112 Pin	Processor		
<b>S80</b>	908	Processor		
	912 80 Pin	Processor		
	912 112 Pin	Processor		
<b>850</b>	Version 1	Eeprom		
	Version 2	Eeprom		
	Version 3	Eeprom		
	Version 4	Eeprom		
<b>960</b>		Eeprom		

<b>Volkswagen</b>				
<b>Golf 3</b>	VDO Version 1	Eeprom		
	VDO Version 1	Cluster-Plug		
	VDO Version 2	Eeprom		
	MM SW 4.0 –6.4	Eeprom		
	MM SW 4.0 –6.4	Cluster-Plug		
	MM SW 3.0 –3.1	Eeprom		
	TRW	Eeprom		
<b>Golf 4</b>	VDO before 2001 Version 1	Eeprom		
	VDO before 2001 Version 2	Eeprom		
	VDO before 2001	Diagnosis-Plug		
	MotoMeter before 2001 Version 1	Eeprom		
	MotoMeter before 2001 Version 2	Eeprom		
	MotoMeter before 2001	Diagnosis-Plug		
	VDO since 2001	Eeprom		
	VDO since 2001	Diagnosis-Plug		
	MotoMeter since 2001	Eeprom		
	MotoMeter since 2001	Diagnosis-Plug		
	VDO since 2002	Eeprom		
	VDO since 2002	Diagnosis-Plug		
	MotoMeter since 2002	Eeprom		
	MotoMeter since 2002	Diagnosis-Plug		
<b>Golf 5</b>		Eeprom		
<b>Gol</b>	South-America	Eeprom		
<b>Bora</b>	VDO before 2001 Version 1	Eeprom		
	VDO before 2001 Version 2	Eeprom		
	VDO before 2001	Diagnosis-Plug		
	MotoMeter before 2001 Version 1	Eeprom		
	MotoMeter before 2001 Versoin 2	Eeprom		
	MotoMeter before 2001	Diagnosis-Plug		
	VDO since 2001	Eeprom		

TACHO-UNIVERSAL

	VDO since 2001	Diagnosis-Plug		
	MotoMeter since 2001	Eeprom		
	MotoMeter since 2001	Diagnosis-Plug		
	VDO since 2002	Eeprom		
	VDO since 2002	Diagnosis-Plug		
	MotoMeter since 2002	Eeprom		
	MotoMeter since 2002	Diagnosis-Plug		
<b>Corrado</b>	VDO	Eeprom		
	VD202	Eeprom		
	MotoMeter	Eeprom		
	MotoMeter SW 1.3-1.8	Eeprom		
	MotoMeter SW 1.3-1.8	Cluster-Plug		
<b>Passat B3</b>	VDO	Eeprom		
	VD202	Eeprom		
	MotoMeter	Eeprom		
	MotoMeter	Cluster-Plug		
	MotoMeter SW 1.3-1.8	Eeprom		
	MotoMeter SW 1.3-1.8	Cluster-Plug		
<b>Passat B5</b>	Magneti Marelli	Diagnosis-Plug		
	VDO Version 1	Eeprom		
	VDO Version 1	Diagnosis-Plug		
	VDO Version 2	Eeprom		
	VDO Version 2	Diagnosis-Plug		
	MotoMeter	Eeprom		
	MotoMeter	Diagnosis-Plug		
<b>Passat B6</b>	VDO Version 1	Eeprom		
	VDO Version 2	Eeprom		
	MotoMeter 2003	Eeprom		
	VDO alle	Diagnosis-Plug		
	MotoMeter 2003	Diagnosis-Plug		
<b>T4</b>	before 10/1998	Eeprom		
	before 10/1998	Cluster-Plug		
	since 10/1998	Eeprom		
	since 10/1998	Diagnosis-Plug		
	Model 2002	Diagnosis-Plug		
<b>Sharan</b>	before Model 2001	Diagnosis-Plug		
	since Model 2001 Version 1	Eeprom		
	since Model 2001 Version 2	Eeprom		
	since Model 2001	Diagnosis-Plug		
	since Model 2002	Diagnosis-Plug		
<b>New Beetle</b>	before Model 2001	Diagnosis-Plug		
	since Model 2001 Version 1	Cluster-Plug		
	since Model 2001 Version 2	Cluster-Plug		

TACHO-UNIVERSAL

	since Model 2001 Version 3	Cluster-Plug		
<b>Lupo</b>	Version 1	Eeprom		
	Version 2	Eeprom		
		Diagnosis-Plug		
<b>Polo</b>	VDO Version 1	Eeprom		
	VDO Version 1	Cluster-Plug		
	VDO Version 2	Eeprom		
	MM SW 4.0 –6.4	Eeprom		
	MM SW 4.0 –6.4	Cluster-Plug		
	MM SW 3.0 –3.1	Eeprom		
	since Model 1998	Eeprom		
	since Model 1998	Diagnosis-Plug		
	TRW	Eeprom		
	TRW 2000	Eeprom		
	VDO 2002	Eeprom		
VDO 2002	Diagnosis-Plug			
TRW 24C08	Eeprom			
<b>Caddy</b>	VDO Version 1	Eeprom		
	VDO Version 1	Cluster-Plug		
	VDO Version 2	Eeprom		
	MM SW 4.0 –6.4	Eeprom		
	MM SW 4.0 –6.4	Cluster-Plug		
	MM SW 3.0 –3.1	Eeprom		
	TRW	Eeprom		
<b>Vento</b>	VDO Version 1	Eeprom		
	VDO Version 1	Cluster-Plug		
	VDO Version 2	Eeprom		
	MM SW 4.0 –6.4	Eeprom		
	MM SW 4.0 –6.4	Cluster-Plug		
	MM SW 3.0 –3.1	Eeprom		
TRW				
<b>LT</b>	VDO before 1999 Version 1	Eeprom		
	VDO before 1999 Version 2	Eeprom		
		Cluster-Plug		
	VDO since 2000	Eeprom		
	Kienzle before 1999	Eeprom		
		Diagnosis-Plug		
	Magneti Marelli Version 1	Processor		
Magneti Marelli Version 2	Processor			
<b>Phaeton</b>	V1	Eeprom		
	V2			
<b>Touareg</b>		Eeprom		
<b>Touran</b>		Eeprom		
<b>Service</b>	all models	Diagnosis-Plug		
<b>Service</b>	CAN Models	Diagnosis-Plug		
<b>1551</b>	erasing the error memory CAN	Diagnosis-Plug		

TACHO-UNIVERSAL

<b>Yamaha</b>	<b>Drag Star</b>		Eeprom		
	<b>Wild Star</b>		Eeprom		
	<b>Phaser</b>		Eeprom		
	<b>T-Max</b>		Eeprom		
	<b>YZF- R1</b>		Eeprom		
	<b>YZF- R6</b>		Eeprom		

**The BMW-Kit for the BMW professional**

<b>Additional module for BMW Programming E46, E38, E39, X5</b>	
<b>Light-Module</b>	Programming about Processor for 912er processors
<b>Light-Module</b>	Programming with Diagnosis-Plug before 912 processors
<b>EWS Module</b>	Erasing about plug
<b>EWS Module</b>	exakte Programmierung über Stecker
<b>Keys</b>	Read out with Keyreader
<b>Keys</b>	Programming
<b>KM-Check</b>	Reading of the values from the cluster, Light-module + EWS with Diagnosis-Plug
<b>TV-Unlocking</b>	Activation of the TV Function (watch TV while you drive) for MK III Systems with Diagnosis-Plug - unlocking BMW TV also works on new Range Rover and Rover 75